

SHUTDOWN PROCEDURE FOR X3B

1. Press **DISABLE ALL** on the motor power panel, which is located on the **Motor Protection Panel** and to the right of Io by two racks.
2. Quit the XDAC program in bnlx3b system, for that just press the red colored button that says **QUIT** and then it will ask a question : “Quit NSLSDAC? Press yes. Shutdown the bnlx3b computer and monitor.
3. Turn off the **CAMAC** power, which is to the right of Io by 1 rack.

STARTUP PROCEDURE FOR X3B

1. Turn on the **CAMAC** power.
2. Restart the bnlx3b computer.
3. Open the XDACv??X.. Icon in the center of the desktop and use the file positions.
4. **Depress the ENABLE ALL switch**, which is located on the **Motor Protection Panel**.

SEE PHOTO IN NEXT PAGE

CAMAC POWER ON/OFF SWITCH

DISABLE ALL MOTORS

