

September 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
		0000 Studies 1 0600 Maint.	0000 Maint. 2 1200 Comm.	0000 Studies 3 1200 Ops.	0000 Ops. 4	0000 Ops. 5	
		CRAMER Mail-in (Gd L-edge)					
0000 Ops. 6	0000 Ops. 7	0000 Ops. 8	0000 Ops. 9	0000 Ops. 10	0000 Ops. 11	0000 Ops. 12	
CRAMER Mail-in			SHI (Metallomics)		AKABAYOV Drive-by		
0000 Ops. 13	0000 Ops. 14 0600 Interl. 1200 Studies	0000 Studies 15 1200 Ops.	0000 Ops. 16	0000 Ops. 17	0000 Ops. 18	0000 Ops. 19	
		PRT (Crystal Testing)					
0000 Ops. 20	0000 Ops. 21 1200 Studies	0000 Studies 22 2000 Templ.	0000 Ops. 23	0000 Ops. 24	0000 Ops. 25	0000 Ops. 26	
PRT			PRT				
0000 Ops. 27	0000 Ops. 28 1200 Studies	0000 Studies 29 0600 Maint.	0000 Maint. 30 1200 Comm.				
PRT							

October 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				0000 Studies 1	0000 Ops. 2	0000 Ops. 3
				1200 Ops. MARONEY (Co, Ni, Zn)		
0000 Ops. 4	0000 Ops. 5	0000 Ops. 6	0000 Ops. 7	0000 Ops. 8	0000 Ops. 9	0000 Ops. 10
MARONEY (Co, Ni, Zn)				QUE (Fe, Mn)		
0000 Ops. 11	0000 Ops. 12	0000 Studies 13	0000 Ops. 14	0000 Ops. 15	0000 Ops. 16	0000 Ops. 17
QUE	0600 Interl. 1200 Studies	1200 Ops. SHI (Metallomics)		SETUP	SAGI/SOLOMONOV	
0000 Ops. 18	0000 Ops. 19	0000 Studies 20	0000 Ops. 21	0000 Ops. 22	0000 Ops. 23	0000 Ops. 24
SAGI (Zn)	1200 Studies	2000 Templ.	SAGI (Zn)	EXAFS WORKSHOP		SAGI
0000 Ops. 25	0000 Ops. 26	0000 Studies 27	0000 Maint. 28	0000 Studies 29	0000 Ops. 30	0000 Ops. 31
SOLOMONOV	1200 Studies	0600 Maint.	1200 Comm.	1200 Ops. TIERNEY (Zn, Co)		

November 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
0000 Ops. 1	0000 Ops. 2	0000 Ops. 3	0000 Ops. 4	0000 Ops. 5	0000 Ops. 6	0000 Ops. 7
TIERNEY (Zn, Co)			BOON (Fe)			
0000 Ops. 8	0000 Ops. 9	0000 Studies 10	0000 Ops. 11	0000 Ops. 12	0000 Ops. 13	0000 Ops. 14
BOON	0600 Interl. 1200 Studies	1200 Ops.	SHI (Metallomics)		PRT	
0000 Ops. 15	0000 Ops. 16	0000 Studies 17	0000 Ops. 18	0000 Ops. 19	0000 Ops. 20	0000 Ops. 21
PRT	1200 Studies	2000 Templ.	PRT (CRYSTAL TESTING)			
0000 Ops. 22	0000 Ops. 23	0000 Maint. 24	0000 Maint. 25	0000 Holiday 26	0000 Holiday 27	0000 Maint. 28
PRT	0600 Maint.					
0000 Maint. 29	0000 Maint. 30					